

# VOLKSWAGEN CRAFTER 35 2.0 Koppaking DEFECT



Itemno 311582  
Kind Van  
Specification Closed Van  
Matriculation year 2015 / 01  
Mileage 193,438 km

**Chassisnumber**  
WV1ZZZ2EZF6021013

Technical condition 

**Remarks**  
Koppaking DEFECT / Head Gasket  
( A15 )



**Price €6950**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,377 kg
Own weight	2,123 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,500 kg
Towing bracket	
Wheelbase	367 cm
Suspension type	spring suspension

### Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	1
Parking assistance	Front and back
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	Silver
Heated mirrors	
Reversing camera	

### Drivetrain

Engine capacity	120 Kw (163 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

### Superstructure

Build kind	L2H2 - Medium wheelbase, Medium roof
Inner box length	333 cm
Inner box width	177 cm
Inner box height	204 cm
Load bed height	68 cm
Netto height	183 cm
Rear step	
Roof-rack	None
Back doors	Double door
Workshop equipment	

### Chairs

Number of seats	3
Seat cover	cloth

### Remarks

Remarks	Koppaking DEFECT / Head Gasket DEFECT!
---------	--

### Tyres/Wheels

Sparewheel	
Spare tire profile	3 mm

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1

Tire size: 235/65R16,0  
spring suspension  
Disc brakes



2

Tire size: 235/65R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements