

MERCEDES-BENZ SPRINTER 516 L3H2 Maxi Autom



Itemno 315335
Kind Van
Specification Closed Van
Matriculation year 2016 / 09
Mileage 99,455 km

Chassisnumber
WDB9066551P301363

Technical condition

Remarks
L3H2 Maxi Automaat Airco Dubbellucht
(A15)

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Twin tires ✓
Own weight 2,834 kg
Gross vehicle weight 5,000 kg
Towing bracket ✓
Wheelbase 433 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control ✓
Tacho ✓
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Partition ✓
GPS navigation ✓
Color white
Heated mirrors ✓
Reversing camera ✓

Drivetrain

Engine capacity 120 Kw (163 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 435 cm
Inner box width 177 cm
Inner box height 192 cm
Load bed height 75 cm
Netto height 183 cm
Rear step ✓
Roof-rack with roll and stairs
Sidedoors 1
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks L3H2 Maxi Automaat Airco
Dubbellucht 163Pk Euro6!

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 205/75R16,0
spring suspension
Disc brakes



2

Tire size: 205/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements