

MERCEDES-BENZ SPRINTER 317 Bakwagen Laadklep



Itemno 315391
Kind Van
Specification Closed box
Matriculation year 2024 / 05
Mileage 4,616 km

Chassisnumber
W1V3K3FZ9RN287278

Technical condition

Remarks

Bakwagen Laadklep, Airco, Navi, Mbox,
(A15)

Price € 47900

KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 955 kg
Own weight 2,545 kg
Gross vehicle weight 3,500 kg
Wheelbase 433 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Number of airbags 2
Parking assistance None
Electric windows ✓
Electric mirrors ✓
GPS navigation ✓
Color white
Reversing camera ✓

Drivetrain

Engine capacity 125 Kw (170 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Manual
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 435 cm
Inner box width 212 cm
Inner box height 211 cm
Load bed height 94 cm
Netto height 204 cm
Roof-rack None
Back doors taillift

Chairs

Number of seats 3
Seat cover cloth

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 750 kg
Tail-lift make Sørensen
Tail-lift size 160x211

Remarks

Remarks Bakwagen Laadklep, Airco,
Navi, Mbox, Camera, Cruise
Control, Euro 6, 170 PK!

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 235/65R16,0
spring suspension
Disc brakes

2



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements