VOLKSWAGEN CADDY 1.4 CGI AARDGAS/BENZINE



Itemno Kind Specification Matriculation year Mileage Chassisnumber WV1ZZZ2KZLX011693

315786 Van Compact panel van 2019/11 107,681 km

KLEYN KLEYN Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12

4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Towing bracket Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Number of airbags Rear wiper Parking assistance Electric windows Electric mirrors Partition Color Heated mirrors

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

4x2 764 kg 1,481 kg 2,245 kg 740 kg 1,300 kg

2

268 cm spring suspension

single cabin

4

None

white

81 Kw (110 Hp) Natural gas 6 Timing belt Manual 6

Superstructure

Build kind

Inner box length Inner box width Inner box heigth Load bed heigth Netto height Roof-rack Sidedoors Back doors

Chairs

Number of seats Seat cover

Remarks Remarks

roof 169 cm 140 cm 120 cm 60 cm 114 cm None 1 Double door

L1H1 - Short wheelbase, Low

2 cloth

AARDGAS/BENZINE EURO6

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassie	
Chassis	
Dashboard display codes	0000
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444


VANS KLEYN KLEYN GROUP KLEYN KLEYN TRAILERS SERVICE

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Disc brakes

Legenda for inspection report Very good state Good state Reasonable state Moderate state

Moderate state Does not meet requirements