

OPEL MOVANO 2.3 DUB.CAB HIAB-029 !



Itemno 316562
Kind Van
Specification Open with sideboards
Matriculation year 2018 / 02
Mileage 153,686 km

Chassisnumber
W0VVSW600JB146601

Technical condition

Remarks
open laadbak, HIAB 029 KRAAN, dubbele
(A15)



Price € 19800

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,250 kg
Own weight	2,250 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Wheelbase	433 cm
Suspension type	spring suspension

Cabin

Cabin type	double cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	1
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
GPS navigation	✓
Color	white
maintenance Guide	✓
Heated mirrors	✓

Drivetrain

Engine capacity	81 Kw (110 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	305 cm
Inner box width	202 cm
Inner box height	40 cm
Load bed height	85 cm
Roof-rack	None
Back doors	taillift

Chairs

Number of seats	7
Seat cover	cloth

Crane

Crane	✓
Crane make	hiab
Year crane	2,017
Capacity crane	1
Maximum load	600 kg bij 4,5m
CE-approved	✓
Log book	✓
Control position	side control right
Crane position	Behind the cabin
Hook	✓

Remarks

Remarks	open laadbak, HIAB 029 KRAAN, dubbele cabine, airco, navi, NAP!
---------	---

Tyres/Wheels

Sparewheel	✓
Spare tire profile	3 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Crane

Supports



Mechanical



Hydraulics



Electrical



Tyres/Wheels

Tyres



Tires and axles



1

5 mm

5 mm

Tire size: 225/65R16,0
coil spring suspension
Disc brakes



2

6 mm

3 mm

Tire size: 225/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

