

RENAULT KANGOO 1.5 koelwagen EURO6



Itemno 317817
Kind Van
Specification Frigo
Matriculation year 2020 / 08
Mileage 117,148 km

Chassisnumber
VF1FW51J162534645

Technical condition

Remarks
koelwagen EURO6 koeling
(A15)

Price €12950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration 4x2
Own weight 1,355 kg
Gross vehicle weight 1,950 kg
Wheelbase 270 cm

Cabin

Cabin type single cabin
Airconditioning
Number of airbags 1
Parking assistance Back
Electric windows
Electric mirrors
Partition
Radio/cassette
Color white
Heated mirrors
Lighting type Halogen lamps
Bluetooth

Drivetrain

Engine capacity 66 Kw (90 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 5
Power steering
ABS
ASR
Starter battery

Superstructure

Build kind L1H1 - Short wheelbase, Low roof
Inner box length 139 cm
Inner box width 129 cm
Inner box height 102 cm
Load bed height 74 cm
Netto height 99 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Doors

Central locking

Chairs

Number of seats 2
Seat cover cloth
Chair adjustment Manually

Refrigeration unit

Enginemake frigo-unit Thermoking
Enginetype frigo-unit B 100
Enginetype frigo-unit Compressor / electrical
Box heater
Type of cooling Cooling
Day/night cooling day and night cooling

Remarks

Remarks koelwagen EURO6 koeling

Tyres/Wheels

Sparewheel
Spare tire profile 5 %
Tire type Summer tyres

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Refrigeration unit

Systems

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 195/65R15
coil spring suspension
Disc brakes



2

Tire size: 195/65R15
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements