

## MERCEDES-BENZ SPRINTER 316 L3H2 Maxi Autom



Itemno 317872  
Kind Van  
Specification Closed Van  
Matriculation year 2021 / 11  
Mileage 486,856 km

**Chassisnumber**  
W1V9076351P406818

Technical condition

**Remarks**  
L3H2 Maxi Automaat Airco 163Pk Export  
( A15 )

**Price € 16600**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Own weight 2,446 kg  
Gross vehicle weight 3,500 kg  
Wheelbase 433 cm  
Suspension type spring suspension

### Cabin

Cabin type single cabin  
Cruise control ✓  
Airconditioning ✓  
Number of airbags 1  
Parking assistance None  
Electric windows ✓  
Electric mirrors ✓  
Partition ✓  
Color white  
Heated mirrors ✓  
Reversing camera ✓

### Drivetrain

Engine capacity 120 Kw (163 Hp)  
Fuel type diesel  
Euro 6  
Distribution type Timing chain  
Gearbox kind Automatic  
Power steering ✓  
ABS ✓  
ASR ✓

### Superstructure

Inner box length 436 cm  
Inner box width 177 cm  
Inner box height 196 cm  
Load bed height 68 cm  
Netto height 183 cm  
Rear step ✓  
Roof-rack None  
Sidedoors 1  
Back doors Double door

### Chairs

Number of seats 3  
Seat cover leather

### Remarks

Remarks L3H2 Maxi Automaat Airco  
163Pk Export Mbus Euro6!

### Tyres/Wheels

Sparewheel ✓

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1  
Tire size: 235/65R16,0  
spring suspension  
Disc brakes



2  
Tire size: 235/65R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements