

FORD TRANSIT 2.0 TDCI 130 L4 LAADKLEP



Itemno 317961
Kind Van
Specification Closed box
Matriculation year 2022 / 11
Mileage 45,488 km

Chassisnumber
WF0AXXTTRANS78123

Technical condition

Remarks
gesloten laadbak, laadklep, spoiler, airco, 45
(A15)

Price € 24900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Wheelbase 393 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Radio/cassette ✓
Color white
maintenance Guide ✓
Heated mirrors ✓
Lighting type Halogen lamps
Speed limiter ✓
Climatecontrol ✓
Bluetooth ✓

Drivetrain

Engine capacity (0 Hp)
Fuel type diesel
Distribution type Timing belt
Gearbox kind Manual
Speed limiter ✓
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓
Starter battery ✓

Superstructure

Build kind L4H1 - Extra long wheelbase,
Low roof
Inner box length 429 cm
Inner box width 203 cm
Inner box height 217 cm
Load bed height 91 cm
Netto height 210 cm
Roof-rack None
Back doors taillift

Doors

Central locking ✓

Chairs

Number of seats 3
Seats configuration 1+2
Seat cover cloth
Chair adjustment Manually

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift make Sorensen
Tail-lift material aluminium
Tail-lift size 212x140

Remarks

Remarks gesloten laadbak, laadklep,
spoiler, airco, 45 dkm.

Tyres/Wheels

Sparewheel ✓
Spare tire profile 8 %
Tire type Summer tyres

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 235/65R16,0
coil spring suspension
Disc brakes

2



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements