

RENAULT MASTER 2.3 Koelwagen Laadklep!



Itemno 318138
Kind Van
Specification Frigo
Matriculation year 2019 / 07
Mileage 129,732 km

Chassisnumber
VF1VB000862039009

Technical condition 

Remarks
koelwagen, D/N, laadklep, airco, zijdeur,
(A15)

Price € 25900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration 4x2
Wheelbase 433 cm

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Radio/cassette ✓
GPS navigation ✓
Color white
maintenance Guide ✓
Lighting type Halogen lamps
Speed limiter ✓
Bluetooth ✓

Drivetrain

Engine capacity (0 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Manual
Speed limiter ✓
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓
Starter battery ✓

Superstructure

Build kind L3H1 - Long wheelbase, Low roof
Woodlined box ✓
Inner box length 381 cm
Inner box width 190 cm
Inner box height 194 cm
Load bed height 96 cm
Netto height 194 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Doors

Central locking ✓

Chairs

Seats configuration 1+2
Seat cover cloth
Chair adjustment Manually

Refrigeration unit

Enginemake frigo-unit Thermoking
Enginetype frigo-unit V300 max
Enginetype frigo-unit Compressor / electrical
Type of cooling Freezing
Day/night cooling day and night cooling

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift make Dhollandia dhle.08
Tail-lift material aluminium
Tail-lift size 145x203

Remarks

Remarks koelwagen, D/N, laadklep, airco, zijdeur, Euro6!

Tyres/Wheels

Tire type Summer tyres

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Refrigeration unit

Systems

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 235/65R16
coil spring suspension
Disc brakes



2

Tire size: 235/65R16
spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements