

MERCEDES-BENZ EVITO L2 66 kWh Long Range



Itemno 318174
Kind Van
Specification Closed Van
Matriculation year 2023 / 03
Mileage 17,609 km

Chassisnumber
W1VVUBFZXP4219815

Technical condition

Remarks

L2, Long Range 66 kWh, 284 km WLTP,
(A15)

Price € 33900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration 4x2
Own weight 2,379 kg
Gross vehicle weight 3,200 kg
Wheelbase 320 cm
Aluminium rims ✓

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Number of airbags 1
Parking heater ✓
Rear wiper ✓
Parking assistance Front and back
Coloured windows ✓
Electric windows ✓
Electric mirrors ✓
Partition ✓
Radio/cassette ✓
Carplay ✓
GPS navigation ✓
Color Black
Metallic ✓
Heated mirrors ✓
Reversing camera ✓
Lighting type Led lamps
Speed limiter ✓
Climatecontrol ✓
Seat heating ✓
Bluetooth ✓

Drivetrain

Engine capacity 70 Kw (95 Hp)
Fuel type electrical
Gearbox kind Automatic
Speed limiter ✓
Power steering ✓
ASR ✓
Starter battery ✓

Superstructure

Build kind L2H1 – Middellange wielbasis, laag dak
Inner box length 249 cm
Inner box width 166 cm
Inner box height 132 cm
Load bed height 64 cm
Netto height 122 cm
Roof-rack None
Sidedoors 1
Side windows 1
Back doors Double door

Doors

Central locking ✓

Chairs

Number of seats 3
Seat cover cloth
Chair adjustment Manually

Remarks

Remarks L2, Long Range 66 kWh, 284 km WLTP, LED, Cruise, Thermotronic, Parktronic, Camera, Lichtmetaal

Tyres/Wheels

Tire type All weather tyres

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/55R17
coil spring suspension
Disc brakes



Tire size: 225/55R17
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements