

VOLKSWAGEN CRAFTER 35 2.0 L2H1 Navi Euro6



Itemno 318220
Kind Van
Specification Closed Van
Matriculation year 2020 / 10
Mileage 100,789 km

Chassisnumber
WV1ZZSYZM9002954

Technical condition

Remarks
L2H1, Airco, Navi, Trekhaak, Euro6, 140
(A15)

Price € 19900



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration 4x2
Own weight 2,063 kg
Gross vehicle weight 3,500 kg
Towing bracket √
Wheelbase 364 cm

Cabin

Cabin type single cabin
Airconditioning √
Number of airbags 1
Parking assistance None
Coloured windows √
Electric windows √
Electric mirrors √
Partition √
Radio/cassette √
GPS navigation √
Color Blue
Heated mirrors √
Lighting type Halogen lamps
Bluetooth √

Drivetrain

Engine capacity 103 Kw (140 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 6
Power steering √
ABS √
ASR √
Starter battery √

Superstructure

Build kind L2H1 – Middellange wielbasis, laag dak
Inner box length 326 cm
Inner box width 175 cm
Inner box height 170 cm
Load bed height 53 cm
Netto height 159 cm
Rear step √
Roof-rack None
Sidedoors 1
Back doors Double door

Doors

Central locking √

Chairs

Number of seats 3
Seats configuration 1+2
Seat cover cloth
Chair adjustment Manually

Remarks

Remarks L2H1, Airco, Navi, Trekhaak, Euro6, 140 PK!

Tyres/Wheels

Sparewheel √
Tire type Summer tyres

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/75R16
coil spring suspension
Disc brakes



Tire size: 205/75R16
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements