

MERCEDES-BENZ ESPRINTER L2H2 41KwH Elektrisch



Itemno 318309
Kind Van
Specification Closed Van
Matriculation year 2021 / 01
Mileage 12,018 km

Chassisnumber
W1V9106331P317411

Technical condition
Remarks
electrisch, L2H2, automaat, airco, 12 dkm.
(A15)

Price € 21750

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks en Bedrijfswagens BV

Maatschappelijke zetel
Groenplaats 14, bus 4
3621 Lanaken
Belgium

Bank: RABO Bank
IBAN:
BE82731064853868
BIC/SWIFT: KREDBEBBXX

BTW / VAT

Equipment

Chassis

Configuration 4x2
Own weight 2,567 kg
Gross vehicle weight 3,500 kg
Wheelbase 392 cm

Cabin

Cabin type single cabin
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Partition ✓
Radio/cassette ✓
Color white
maintenance Guide ✓
Heated mirrors ✓
Reversing camera ✓
Lighting type Halogen lamps
Seat heating ✓
Bluetooth ✓

Drivetrain

Engine capacity 70 Kw (95 Hp)
Fuel type electrical
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓
Starter battery ✓

Superstructure

Build kind L2H2 - Medium wheelbase,
Medium roof
Inner box length 330 cm
Inner box width 176 cm
Inner box height 200 cm
Load bed height 70 cm
Netto height 191 cm
Rear step ✓
Roof-rack None
Sidedoors 1
Back doors Double door

Doors

Central locking ✓

Chairs

Number of seats 3
Seat cover cloth
Chair adjustment Manually

Remarks

Remarks electrisch, L2H2, automaat,
airco, 12 dkm.

Tyres/Wheels

Tire type Summer tyres

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks en Bedrijfswagens BV

Maatschappelijke zetel
Groenplaats 14, bus 4
3621 Lanaken
Belgium

Bank: RABO Bank
IBAN:
BE82731064853868
BIC/SWIFT: KREDBEBBXX

BTW / VAT

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 225/75R16
coil spring suspension
Disc brakes



2
Tire size: 225/75R16
spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements