

VOLKSWAGEN TRANSPORTER 2.0 TDI T6.1 L1H1 1



Itemno 318529
Kind Van
Specification Closed Van
Matriculation year 2021 / 02
Mileage 153,138 km

Chassisnumber
WV1ZZZ7HZMX005104

Technical condition

Remarks
T6.1 L1H1 Navi Euro6 150Pk Airco
(A15)

Price € 18750

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration	4x2
Loading Capacity	970 kg
Own weight	1,830 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	✓
Wheelbase	300 cm

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Partition	✓
Radio/cassette	✓
Carplay	✓
GPS navigation	✓
Color	Gray
Metallic	✓
Heated mirrors	✓
Lighting type	Halogen lamps
Bluetooth	✓

Drivetrain

Engine capacity	110 Kw (149 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	5
Power steering	✓
ABS	✓
ASR	✓
Starter battery	✓

Superstructure

Build kind	L1H1 - Short wheelbase, Low roof
Inner box length	245 cm
Inner box width	157 cm
Inner box height	131 cm
Load bed height	55 cm
Netto height	128 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door
Workshop equipment	✓

Doors

Central locking	✓
-----------------	---

Chairs

Number of seats	3
Seats configuration	1+2
Seat cover	cloth
Chair adjustment	Manually

Remarks

Remarks	T6.1 L1H1 Navi Euro6 150Pk Airco Wp-Inrichting 3-Zits Deuren Trekhaak 1e Eigenaar!
---------	--

Tyres/Wheels

Sparewheel	✓
Tire type	Winter tyres

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 205/65R16
coil spring suspension
Disc brakes



2

Tire size: 205/65R16
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements