

MERCEDES-BENZ SPRINTER 211 L2H2 Automaat E



Itemno 318545
Kind Van
Specification Closed Van
Matriculation year 2018 / 06
Mileage 163,969 km

Chassisnumber
WDB9066131P612155

Technical condition

Remarks
L2H2 Automaat Euro6 Airco Imperiaal-Trap
(A15)

Price € 16900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration	4x2
Loading Capacity	909 kg
Own weight	2,091 kg
Gross vehicle weight	3,000 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	✓
Wheelbase	367 cm

Cabin

Cabin type	single cabin
Airconditioning	✓
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Partition	✓
Radio/cassette	✓
GPS navigation	✓
Color	white
maintenance Guide	✓
Lighting type	Halogen lamps
Bluetooth	✓

Drivetrain

Engine capacity	84 Kw (114 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓
Starter battery	✓

Superstructure

Build kind	L2H2 - Medium wheelbase, Medium roof
Inner box length	330 cm
Inner box width	176 cm
Inner box height	191 cm
Load bed height	68 cm
Netto height	181 cm
Rear step	✓
Roof-rack	with roll and stairs
Sidedoors	1
Back doors	Double door

Doors

Central locking	✓
-----------------	---

Chairs

Number of seats	3
Seats configuration	1+2
Seat cover	cloth
Chair adjustment	Manually

Remarks

Remarks	L2H2 Automaat Euro6 Airco Imperiaal-Trap Trekhaak!
---------	--

Tyres/Wheels

Tire type	All weather tyres
-----------	-------------------

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 235/65R16
spring suspension
Disc brakes



2

Tire size: 235/65R16
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements