

## ISUZU D-MAX 1.9D ac automaat EURO6



Itemno 318550  
Kind Van  
Specification Pickup  
Matriculation year 2017 / 04  
Mileage 245,501 km

**Chassisnumber**  
MPATFS87JHT001553

Technical condition

**Remarks**  
ac automaat EURO6  
( A15 )



**Price € 16950**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

|                                     |          |
|-------------------------------------|----------|
| Configuration                       | 4x4      |
| Loading Capacity                    | 1,305 kg |
| Own weight                          | 1,735 kg |
| Gross vehicle weight                | 3,040 kg |
| Unbraked towing capacity            | 750 kg   |
| Braked towing capacity, center axle | 2,000 kg |
| Towing bracket                      | ✓        |
| Wheelbase                           | 350 cm   |

### Cabin

|                    |               |
|--------------------|---------------|
| Cruise control     | ✓             |
| Airconditioning    | ✓             |
| Number of airbags  | 6             |
| Parking assistance | None          |
| Electric windows   | ✓             |
| Electric mirrors   | ✓             |
| Partition          | ✓             |
| GPS navigation     | ✓             |
| Color              | Anthracite    |
| Metallic           | ✓             |
| Heated mirrors     | ✓             |
| Reversing camera   | ✓             |
| Lighting type      | Halogen lamps |
| Climatecontrol     | ✓             |
| Bluetooth          | ✓             |
| Flashing lights    | ✓             |

### Drivetrain

|                   |                |
|-------------------|----------------|
| Engine capacity   | 92 Kw (125 Hp) |
| Fuel type         | diesel         |
| Euro              | 6              |
| Distribution type | Timing chain   |
| Gearbox kind      | Automatic      |
| Power steering    | ✓              |
| ABS               | ✓              |
| ASR               | ✓              |
| Starter battery   | ✓              |

### Superstructure

|                  |                                        |
|------------------|----------------------------------------|
| Build kind       | L2H1 – Middellange wielbasis, laag dak |
| Inner box length | 178 cm                                 |
| Inner box width  | 151 cm                                 |
| Inner box height | 48 cm                                  |
| Load bed height  | 81 cm                                  |
| Roof-rack        | None                                   |
| Back doors       | taillift                               |

### Doors

|                 |   |
|-----------------|---|
| Central locking | ✓ |
|-----------------|---|

### Chairs

|                     |          |
|---------------------|----------|
| Number of seats     | 2        |
| Seats configuration | 1+1      |
| Seat cover          | cloth    |
| Chair adjustment    | Manually |

### Taillift

|                      |   |
|----------------------|---|
| Battery loading ramp | ✓ |
|----------------------|---|

### Remarks

|         |                   |
|---------|-------------------|
| Remarks | ac automaat EURO6 |
|---------|-------------------|

### Tyres/Wheels

|                    |                   |
|--------------------|-------------------|
| Sparewheel         | ✓                 |
| Spare tire profile | 4 %               |
| Tire type          | All weather tyres |

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1  
Tire size: 255/60R18  
coil spring suspension  
Disc brakes



2  
Tire size: 255/60R18  
spring suspension  
Drum brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements