

NISSAN NAVARA 2.3 DCI ac EURO6



Itemno 318553
Kind Van
Specification Pickup
Matriculation year 2020 / 03
Mileage 113,994 km

Chassisnumber
VSKBTND23U0139254

Technical condition

Remarks
ac EURO6 camera 4WD navi
(A15)

Price € 20950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration	4x4
Loading Capacity	1,205 kg
Own weight	1,995 kg
Gross vehicle weight	3,200 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,500 kg
Towing bracket	✓
Wheelbase	315 cm
Aluminium rims	✓

Cabin

Cabin type	double cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	2
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Partition	✓
Carplay	✓
GPS navigation	✓
Color	white
Reversing camera	✓
Lighting type	Halogen lamps
Speed limiter	✓
Bluetooth	✓
Flashing lights	✓

Drivetrain

Engine capacity	120 Kw (163 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Speed limiter	✓
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓
Starter battery	✓

Superstructure

Build kind	L2H1 – Middellange wielbasis, laag dak
Inner box length	180 cm
Inner box width	155 cm
Inner box height	96 cm
Load bed height	84 cm
Netto height	85 cm
Roof-rack	standard
Sidedoors	2
Back doors	taillift
Workshop equipment	✓

Doors

Central locking	✓
-----------------	---

Chairs

Number of seats	2
Seats configuration	1+1
Seat cover	cloth
Chair adjustment	Manually

Remarks

Remarks	ac EURO6 camera 4WD navi
---------	--------------------------

Tyres/Wheels

Sparewheel	✓
------------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 255/65R17
coil spring suspension
Disc brakes



Tire size: 255/65R17
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements