

MERCEDES-BENZ EVITO L2 41 kWh Automaat!



Itemno 318671
Kind Van
Specification Closed Van
Matriculation year 2020 / 02
Mileage 41,729 km

Chassisnumber
W1V44760313703213

Technical condition

Remarks
L2 41 kWh Automaat Airco BPM-Vrij
(A15)

Price € 12900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration 4x2
Wheelbase 320 cm

Cabin

Cabin type single cabin
Airconditioning ✓
Number of airbags 2
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Partition ✓
Radio/cassette ✓
GPS navigation ✓
Color white
Heated mirrors ✓
Reversing camera ✓
Lighting type Halogen lamps
Seat heating ✓
Bluetooth ✓

Drivetrain

Engine capacity (0 Hp)
Fuel type electrical
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓
Starter battery ✓

Superstructure

Inner box length 249 cm
Inner box width 166 cm
Inner box height 133 cm
Load bed height 65 cm
Netto height 122 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Doors

Central locking ✓

Chairs

Seat cover cloth
Chair adjustment Manually

Remarks

Remarks L2 41 kWh Automaat Airco
BPM-Vrij Emissie-Vrij!

Tyres/Wheels

Sparewheel ✓
Spare tire profile 6 %
Tire type All weather tyres

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/55R17
coil spring suspension
Disc brakes



Tire size: 225/55R17
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements