

MERCEDES-BENZ SPRINTER 516 KOELING EURO6



Itemno 311992
Kind Van
Specification Frigo
Matriculation year 2017 / 02
Mileage 153,111 km

Chassisnumber
WDB9061531N687733

Technical condition

Remarks

KOELING CARRIER AC AUTOMAAT
(A15)



Price € 19950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Twin tires ✓
Loading Capacity 460 kg
Own weight 3,040 kg
Gross vehicle weight 3,500 kg
Wheelbase 367 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Color Yellow
Heated mirrors ✓

Drivetrain

Engine capacity 120 Kw (163 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Build kind L2H1 – Middellange wielbasis, laag dak
Inner box length 226 cm
Inner box width 205 cm
Inner box height 200 cm
Load bed height 98 cm
Rear step ✓
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit Pulsor 400 mt
Enginetype frigo-unit fuel and electrical
Type of cooling Cooling and freezing
Day/night cooling day and night cooling

Remarks

Remarks KOELING CARRIER AC AUTOMAAT EURO6!!

Tyres/Wheels

Sparewheel ✓

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 195/75R16,0
spring suspension
Disc brakes



Tire size: 195/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements