

## FORD TRANSIT 350 AC NAVI CAMERA EURO6



Itemno 313551  
Kind Van  
Specification Closed Van  
Matriculation year 2021 / 09  
Mileage 106,861 km

**Chassisnumber**  
WF0EXXTTREM87769

Technical condition

**Remarks**  
AC NAVI CAMERA CRUISE EURO6  
( A15 )

**Price €17950**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Loading Capacity 1,028 kg  
Own weight 2,472 kg  
Gross vehicle weight 3,500 kg  
Unbraked towing capacity 750 kg  
Braked towing capacity, center axle 2,750 kg  
Wheelbase 375 cm  
Suspension type spring suspension

### Cabin

Cruise control  
Airconditioning  
Number of airbags 2  
Parking assistance Front and back  
Electric windows  
Electric mirrors  
Partition  
GPS navigation  
Color white  
Reversing camera

### Drivetrain

Engine capacity 95 Kw (129 Hp)  
Fuel type diesel  
Euro 6  
Distribution type Timing belt  
Gearbox kind Manual  
Number of Gears 6  
Power steering  
ABS  
ASR

### Superstructure

Build kind L3H2 - Long wheelbase, Medium roof  
Inner box length 345 cm  
Inner box width 174 cm  
Inner box height 186 cm  
Load bed height 63 cm  
Roof-rack None  
Back doors Double door

### Chairs

Number of seats 3  
Seat cover cloth

### Remarks

Remarks AC NAVI CAMERA CRUISE EURO6

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 235/65R16,0  
coil spring suspension  
Disc brakes



Tire size: 235/65R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements