

IVECO DAILY 35S18 Koelwagen Laadklep



Itemno 314735
Kind Van
Specification Frigo
Matriculation year 2018 / 05
Mileage 277,335 km

Chassisnumber
ZCFC135DX0D608035

Technical condition

Remarks
Koelwagen Laadklep Automaat 180Pk
(A15)

Price € 15600

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 615 kg
Own weight 2,885 kg
Gross vehicle weight 3,500 kg
Braked towing capacity, center axle 3,500 kg
Wheelbase 352 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
GPS navigation ✓
Color white
Heated mirrors ✓
Reversing camera ✓

Drivetrain

Engine capacity 132 Kw (179 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 341 cm
Inner box width 207 cm
Inner box height 200 cm
Load bed height 82 cm
Roof-rack None
Sidedoors 1
Back doors taillift

Chairs

Number of seats 3
Seat cover cloth

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit Pulsor 400
Enginetype frigo-unit fuel and electrical
Type of cooling Cooling and freezing
Day/night cooling day and night cooling

Remarks

Remarks Koelwagen Laadklep Automaat 180Pk Euro6!

Tyres/Wheels

Sparewheel ✓

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Superstructure



Internal condition



External condition



Refrigeration unit

Systems



Tyres/Wheels

Tyres



1



Tire size: 225/65R16,0
spring suspension
Disc brakes

2



Tire size: 0/0R0,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements