

VOLKSWAGEN CRAFTER 35 2.0 L3H3 2xZijdeur LED



Itemno 314889
Kind Van
Specification Closed Van
Matriculation year 2024 / 11
Mileage 10 km

Chassisnumber
WV1ZZZSY1S9023506

Technical condition

Remarks
L3H3 2xZijdeur LED 177Pk Facelift Clima
(A15)

Price € 44900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,391 kg
Own weight	2,109 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,000 kg
Wheelbase	364 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	6
Parking assistance	Front and back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	white
Heated mirrors	✓
Reversing camera	✓

Drivetrain

Engine capacity	130 Kw (177 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	327 cm
Inner box width	177 cm
Inner box height	197 cm
Load bed height	65 cm
Netto height	184 cm
Rear step	✓
Roof-rack	None
Sidedoors	2
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	L3H3 2xZijdeur LED 177Pk Facelift Clima Automaat Euro6 Nieuw BPM-VRIJ Direct-Leverbaar!
---------	--

Tyres/Wheels

Sparewheel	✓
------------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes 

Electrical 

Cabin

Internal 

External 

Steering column 

Suspension 

Chassis 

Wheelsuspension 

Brakes 

Drivetrain

Engine, general 

Cooling system 

Fuel system 

Exhaust system 

Greasing system 

Gearbox 

Clutch 

Drivetrain 

Superstructure

Internal condition 

External condition 

Tyres/Wheels

Tyres 

Tires and axles



Tire size: 235/65R16,0
coil spring suspension
Disc brakes



Tire size: 0/0R0,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

 Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements