

MERCEDES-BENZ CITAN 109 CDI AC EURO6



Itemno 315384
 Kind Van
 Specification Compact panel van
 Matriculation year 2021 / 04
 Mileage 344,694 km
Chassisnumber
 W1V4156031U295549
 Technical condition 
Remarks
 AC EURO6
 (A15)



Price € 7950



Kleyn Vans B.V.®
 P.O. Box 3
 4214 ZJ Vuren
 Zeiving 12
 4214 KT Vuren
 The Netherlands

IBAN: NL32RABO0317847430
 SWIFT/BIC: RABONL2U

KvK 11044363
 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Loading Capacity 610 kg
 Own weight 1,370 kg
 Gross vehicle weight 1,980 kg
 Unbraked towing capacity 700 kg
 Braked towing capacity, center axle 1,050 kg
 Wheelbase 270 cm
 Suspension type coil spring suspension

Cabin

Cabin type single cabin
 Cruise control ✓
 Airconditioning ✓
 Number of airbags 1
 Parking assistance Back
 Electric windows ✓
 Electric mirrors ✓
 Partition ✓
 Color Black
 Heated mirrors ✓

Drivetrain

Engine capacity 70 Kw (95 Hp)
 Fuel type diesel
 Euro 6
 Distribution type Timing belt
 Gearbox kind Manual
 Number of Gears 6
 Power steering ✓
 ABS ✓
 ASR ✓

Superstructure

Build kind L2H1 – Middellange wielbasis, laag dak
 Inner box length 163 cm
 Inner box width 144 cm
 Inner box height 119 cm
 Load bed height 57 cm
 Netto height 112 cm
 Roof-rack None
 Sidedoors 1
 Back doors Double door

Chairs

Number of seats 3
 Seat cover cloth

Remarks

Remarks AC EURO6

Tyres/Wheels

Sparewheel ✓
 Spare tire profile 6 mm

Contact information




info@kleyn.com
 Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 195/65R16,0
coil spring suspension
Disc brakes



Tire size: 195/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements