

FORD TRANSIT CONNECT L1 Navi Euro6 NAP!



Itemno 315609
Kind Van
Specification Compact panel van
Matriculation year 2020 / 07
Mileage 102,717 km

Chassisnumber
WF0RXXWPGRLA39961

Technical condition

Remarks
L1 Navi Euro6 NAP Airco Trekhaak
(A15)



Price € 11250

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	708 kg
Own weight	1,467 kg
Gross vehicle weight	2,175 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	1,200 kg
Towing bracket	✓
Wheelbase	266 cm
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	4
Parking assistance	Back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	white
Heated mirrors	✓
Reversing camera	✓

Drivetrain

Engine capacity	55 Kw (75 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	163 cm
Inner box width	126 cm
Inner box height	121 cm
Load bed height	52 cm
Netto height	115 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	L1 Navi Euro6 NAP Airco Trekhaak Sidebars Camera OH-Historie 1e Eigenaar!
---------	---

Tyres/Wheels

Sparewheel	✓
Spare tire profile	5 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 215/55R16,0
coil spring suspension
Disc brakes



2
Tire size: 215/55R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements