

MERCEDES-BENZ SPRINTER 311 XXL AC AUTOMA



Itemno 315705
Kind Van
Specification Closed Van
Matriculation year 2016 / 06
Mileage 115,654 km

Chassisnumber
WDB9066371P299303

Technical condition

Remarks
XXL L4 AC AUTOMAAT EURO6
(A15)



Price € 19950

KLEYN VANS

KLEYN GROUP KLEYN TRUCKS KLEYN TRAILERS KLEYN SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	799 kg
Own weight	2,401 kg
Gross vehicle weight	3,200 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Wheelbase	433 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Airconditioning	✓
Number of airbags	1
Parking assistance	Front and back
Electric windows	✓
Electric mirrors	✓
GPS navigation	✓
Color	Blue
Heated mirrors	✓
Reversing camera	✓

Drivetrain

Engine capacity	84 Kw (114 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	L3H2 - Long wheelbase, Medium roof
Inner box length	480 cm
Inner box width	174 cm
Inner box height	197 cm
Load bed height	64 cm
Netto height	183 cm
Rear step	✓
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	XXL L4 AC AUTOMAAT EURO6
---------	--------------------------

Tyres/Wheels

Sparewheel	✓
Spare tire profile	6 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 235/65R16,0
spring suspension
Disc brakes



2
Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements