

## VOLKSWAGEN CADDY 2.0 TDI 150 DSG AUT.



Itemno 316113  
Kind Van  
Specification Compact panel van  
Matriculation year 2020 / 09  
Mileage 411,471 km

Chassisnumber  
WV1ZZZ2KZLX121712

Technical condition

Remarks  
airco, DSG AUT. navi  
( A15 )



**Price € 7800**

# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

|                                     |                        |
|-------------------------------------|------------------------|
| Number of axles                     | 2                      |
| Configuration                       | 4x2                    |
| Loading Capacity                    | 776 kg                 |
| Own weight                          | 1,514 kg               |
| Gross vehicle weight                | 2,290 kg               |
| Unbraked towing capacity            | 750 kg                 |
| Braked towing capacity, center axle | 1,500 kg               |
| Wheelbase                           | 268 cm                 |
| Suspension type                     | coil spring suspension |

### Cabin

|                    |              |
|--------------------|--------------|
| Cabin type         | single cabin |
| Cruise control     | ✓            |
| Airconditioning    | ✓            |
| Number of airbags  | 1            |
| Rear wiper         | ✓            |
| Parking assistance | Back         |
| Electric windows   | ✓            |
| Electric mirrors   | ✓            |
| Partition          | ✓            |
| GPS navigation     | ✓            |
| Color              | white        |
| Heated mirrors     | ✓            |

### Drivetrain

|                   |                 |
|-------------------|-----------------|
| Engine capacity   | 110 Kw (149 Hp) |
| Fuel type         | diesel          |
| Euro              | 6               |
| Distribution type | Timing belt     |
| Gearbox kind      | Automatic       |
| Power steering    | ✓               |
| ABS               | ✓               |
| ASR               | ✓               |

### Superstructure

|                  |          |
|------------------|----------|
| Inner box length | 170 cm   |
| Inner box width  | 145 cm   |
| Inner box height | 121 cm   |
| Load bed height  | 60 cm    |
| Netto height     | 111 cm   |
| Roof-rack        | None     |
| Sidedoors        | 1        |
| Side windows     | 1        |
| Back doors       | taillift |

### Chairs

|                 |       |
|-----------------|-------|
| Number of seats | 2     |
| Seat cover      | cloth |

### Remarks

|         |                      |
|---------|----------------------|
| Remarks | airco, DSG AUT. navi |
|---------|----------------------|

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 205/55R16,0  
coil spring suspension  
Disc brakes



Tire size: 205/55R16,0  
coil spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements