

MERCEDES-BENZ CITAN 110 CDI L1 Airco Pro Euro6



Itemno 316156
Kind Van
Specification Compact panel van
Matriculation year 2022 / 08
Mileage 22,151 km

Chassisnumber
W1V4206231U321025

Technical condition

Remarks
L1 Airco Euro6 Lm-Velgen Nieuw-Type!
(A15)

Price € 13900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 538 kg
Own weight 1,483 kg
Gross vehicle weight 2,021 kg
Unbraked towing capacity 740 kg
Braked towing capacity, center axle 1,500 kg
Wheelbase 272 cm
Suspension type coil spring suspension

Cabin

Cabin type single cabin
Airconditioning ✓
Number of airbags 4
Parking assistance Back
Electric mirrors ✓
Partition ✓
Color white
Heated mirrors ✓

Drivetrain

Engine capacity 70 Kw (95 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 171 cm
Inner box width 144 cm
Inner box height 121 cm
Load bed height 58 cm
Netto height 112 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 2
Seat cover cloth

Remarks

Remarks L1 Airco Euro6 Lm-Velgen
Nieuw-Type!

Tyres/Wheels

Sparewheel ✓
Spare tire profile 6 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/60R16,0
coil spring suspension
Disc brakes



Tire size: 205/60R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements