

MERCEDES-BENZ SPRINTER 314 L2H1 Xenon Euro6



Itemno 316350
Kind Van
Specification Closed Van
Matriculation year 2017 / 04
Mileage 175,020 km

Chassisnumber
WDB9066331P399758

Technical condition

Remarks
L2H1 Xenon Euro6 Trekhaak Camera
(A15)

Price €14450

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 1,114 kg
Own weight 2,086 kg
Gross vehicle weight 3,200 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 2,000 kg
Towing bracket
Wheelbase 367 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Airconditioning
Number of airbags 2
Parking assistance None
Electric mirrors
Partition
Color white
Heated mirrors
Reversing camera

Drivetrain

Engine capacity 105 Kw (143 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Manual
Number of Gears 6
Power steering
ABS
ASR

Superstructure

Inner box length 330 cm
Inner box width 176 cm
Inner box height 163 cm
Load bed height 67 cm
Netto height 154 cm
Rear step
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks L2H1 Xenon Euro6 Trekhaak Camera 143pk!

Tyres/Wheels

Sparewheel
Spare tire profile 5 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 235/65R16,0
spring suspension
Disc brakes



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements