

MERCEDES-BENZ SPRINTER 314 Bakwagen Laadkl



Itemno 316944
Kind Van
Specification Closed box
Matriculation year 2020 / 04
Mileage 153,647 km

Chassisnumber
W1V9071351N084606

Technical condition

Remarks
gesloten laadbak, laadklep, zijdeur,
(A15)



Price € 23900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 720 kg
Own weight 2,780 kg
Gross vehicle weight 3,500 kg
Wheelbase 433 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Color Green
maintenance Guide ✓
Reversing camera ✓

Drivetrain

Engine capacity 105 Kw (143 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 443 cm
Inner box width 213 cm
Inner box height 222 cm
Load bed height 94 cm
Netto height 221 cm
Roof-rack None
Sidedoors 1
Back doors taillift

Chairs

Number of seats 2
Seat cover cloth

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 1,000 kg
Tail-lift make dhollandia dhlm 10
Tail-lift size 160x218

Remarks

Remarks gesloten laadbak, laadklep,
zijdeur, automaat, airco,
camera,

Tyres/Wheels

Sparewheel ✓

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 235/65R16,0
spring suspension
Disc brakes

2



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements