

MERCEDES-BENZ VITO 122 CDI ac aut V6 3.0 ltr



Itemno 317090
Kind Van
Specification Closed Van
Matriculation year 2013 / 06
Mileage 222,951 km

Chassisnumber
WDF63960313817128

Technical condition

Remarks
ac aut V6 3.0 ltr
(A15)

Price € 11750

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	890 kg
Own weight	1,910 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	✓
Wheelbase	320 cm
Aluminium rims	✓
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	1
Parking assistance	Front and back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	Gray
Metallic	✓
Heated mirrors	✓

Drivetrain

Engine capacity	165 Kw (224 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing chain
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	253 cm
Inner box width	164 cm
Inner box height	132 cm
Load bed height	58 cm
Netto height	122 cm
Roof-rack	standard
Sidedoors	1
Back doors	taillift

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	ac aut V6 3.0 ltr
---------	-------------------

Tyres/Wheels

Sparewheel	✓
Spare tire profile	6 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/55R17,0
coil spring suspension
Disc brakes



Tire size: 225/55R17,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements