

MERCEDES-BENZ SPRINTER 317 L2H2 Koeler 3.5t-



Itemno 317368
Kind Van
Specification Frigo
Matriculation year 2024 / 06
Mileage 856 km

Chassisnumber
W1V3KBFZ6RP660386

Technical condition

Remarks
L2H2, Koelwagen/Vriezer, 3.5t-Trekhaak,
(A15)

Price € 62750

KLEYN VANS

KLEYN **KLEYN** **KLEYN** **KLEYN**
GROUP TRUCKS TRAILERS SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,300 kg
Own weight	2,200 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,500 kg
Towing bracket	✓
Wheelbase	367 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Airconditioning	✓
Number of airbags	1
Parking assistance	None
Electric windows	✓
Partition	✓
Color	white
Heated mirrors	✓
Reversing camera	✓

Drivetrain

Engine capacity	125 Kw (170 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	309 cm
Inner box width	160 cm
Inner box height	179 cm
Load bed height	69 cm
Rear step	✓
Roof-rack	None
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Refrigeration unit

Enginemade frigo-unit	Thermoking
Enginetype frigo-unit	V-200-Max
Enginetype frigo-unit	fuel
Type of cooling	Cooling and freezing

Remarks

Remarks	L2H2, Koelwagen/Vriezer, 3.5t-Trekhaak, D/N Aansluiting, Mbox, Airco, Camera, Euro 6, 170 PK!
---------	--

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes ●●●●●●

Electrical ●●●●●●

Cabin

Internal ●●●●●●

External ●●●●●●

Steering column ●●●●●●

Suspension ●●●●●●

Chassis ●●●●●●

Brakes ●●●●●●

Drivetrain

Engine, general ●●●●●●

Cooling system ●●●●●●

Fuel system ●●●●●●

Exhaust system ●●●●●●

Greasing system ●●●●●●

Gearbox ●●●●●●

Clutch ●●●●●●

Drivetrain ●●●●●●

Superstructure

Superstructure ●●●●●●

Internal condition ●●●●●●

External condition ●●●●●●

Refrigeration unit

Systems ●●●●●●

Tires and axles



Tire size: 0/0R16,0
spring suspension
Disc brakes



Tire size: 0/0R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

●●●●●● Very good state
●●●●●● Good state
●●●●●● Reasonable state
●●●●●● Moderate state
●●●●●● Does not meet requirements