

OPEL MOVANO 2.3 L2H2 Imperiaal Navi!



Itemno 317661
Kind Van
Specification Closed Van
Matriculation year 2019 / 12
Mileage 111,472 km

Chassisnumber
W0VMR3603LB207318

Technical condition

Remarks
L2H2 Imperiaal-Trap Airco/ECC Navi
(A15)



Price € 15800

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,551 kg
Own weight	1,949 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	✓
Wheelbase	368 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	2
Parking assistance	Back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	white
maintenance Guide	✓
Heated mirrors	✓

Drivetrain

Engine capacity	110 Kw (149 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	305 cm
Inner box width	176 cm
Inner box height	193 cm
Load bed height	57 cm
Netto height	183 cm
Rear step	✓
Roof-rack	with roll and stairs
Sidedoors	1
Back doors	Double door
Workshop equipment	✓

Chairs

Number of seats	3
Seat cover	cloth
Comfort seat	left

Remarks

Remarks	L2H2 Imperiaal-Trap Airco/ECC Navi Trekhaak Sidebars Euro6 1e Eigenaar!
---------	---

Tyres/Wheels

Sparewheel	✓
Spare tire profile	1 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/65R16,0
coil spring suspension
Disc brakes



Tire size: 225/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements