

FORD TRANSIT 2.0 L2H2 Dubbel Cabine!



Itemno 317722
Kind Van
Specification Closed Van
Matriculation year 2018 / 10
Mileage 51,698 km

Chassisnumber
WF0KXXTTGKHE66197

Technical condition

Remarks

L2H2 Dubbel Cabine Airco 130Pk Euro6
(A15)



Price €19800

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 1,184 kg
Own weight 2,181 kg
Gross vehicle weight 3,365 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 2,800 kg
Towing bracket
Wheelbase 330 cm
Suspension type spring suspension

Cabin

Cabin type double cabin
Cruise control
Airconditioning
Number of airbags 2
Parking assistance Front and back
Electric windows
Electric mirrors
Partition
Color white
maintenance Guide
Heated mirrors
Reversing camera

Drivetrain

Engine capacity 96 Kw (130 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 6
Power steering
ABS
ASR

Superstructure

Inner box length 184 cm
Inner box width 168 cm
Inner box height 182 cm
Load bed height 76 cm
Netto height 169 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 6
Seats configuration 3+3
Seat cover skai

Remarks

Remarks L2H2 Dubbel Cabine Airco
130Pk Euro6 Camera
Trekhaak!

Tyres/Wheels

Sparewheel
Spare tire profile 4 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 235/65R16,0
coil spring suspension
Disc brakes



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements