

MERCEDES-BENZ V-KLASSE 250 CDI XL DC EURO



Itemno 317968
Kind Van
Specification Closed Van
Matriculation year 2018 / 07
Mileage 251,340 km

Chassisnumber
WDF44781513469164

Technical condition

Remarks
XL dubel cabine ac automaat
(A15)



Price € 28950

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	840 kg
Own weight	2,360 kg
Gross vehicle weight	3,200 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	✓
Wheelbase	343 cm
Aluminium rims	✓
Suspension type	coil spring suspension

Cabin

Cabin type	double cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	6
Rear wiper	✓
Parking assistance	Front and back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	Black
Metallic	✓
Reversing camera	✓

Drivetrain

Engine capacity	140 Kw (190 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	L3H1 - Long wheelbase, Low roof
Inner box length	161 cm
Inner box width	142 cm
Inner box height	129 cm
Load bed height	54 cm
Netto height	119 cm
Roof-rack	standard
Sidedoors	2
Side windows	2
Back doors	taillift

Chairs

Number of seats	5
Seat cover	leather

Remarks

Remarks	XL dubel cabine ac automaat
---------	-----------------------------

Tyres/Wheels

Sparewheel	✓
------------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 245/45R19,0
coil spring suspension
Disc brakes



Tire size: 245/45R19,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements