

## MERCEDES-BENZ VITO 114 ac automaat EURO6



Itemno 317970  
Kind Van  
Specification Closed Van  
Matriculation year 2019 / 06  
Mileage 189,715 km

**Chassisnumber**  
WDF44760313621089

Technical condition

**Remarks**  
ac automaat EURO6 cruise control  
( A15 )

**Price € 15950**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

|                                     |                        |
|-------------------------------------|------------------------|
| Number of axles                     | 2                      |
| Configuration                       | 4x2                    |
| Loading Capacity                    | 1,228 kg               |
| Own weight                          | 1,972 kg               |
| Gross vehicle weight                | 3,200 kg               |
| Unbraked towing capacity            | 750 kg                 |
| Braked towing capacity, center axle | 2,000 kg               |
| Wheelbase                           | 320 cm                 |
| Suspension type                     | coil spring suspension |

### Cabin

|                    |                |
|--------------------|----------------|
| Cabin type         | single cabin   |
| Cruise control     | ✓              |
| Airconditioning    | ✓              |
| Number of airbags  | 2              |
| Rear wiper         | ✓              |
| Parking assistance | Front and back |
| Electric windows   | ✓              |
| Electric mirrors   | ✓              |
| Partition          | ✓              |
| GPS navigation     | ✓              |
| Color              | white          |
| Reversing camera   | ✓              |

### Drivetrain

|                   |                 |
|-------------------|-----------------|
| Engine capacity   | 100 Kw (136 Hp) |
| Fuel type         | diesel          |
| Euro              | 6               |
| Distribution type | Timing chain    |
| Gearbox kind      | Automatic       |
| Power steering    | ✓               |
| ABS               | ✓               |
| ASR               | ✓               |

### Superstructure

|                  |                                        |
|------------------|----------------------------------------|
| Build kind       | L2H1 – Middellange wielbasis, laag dak |
| Inner box length | 224 cm                                 |
| Inner box width  | 164 cm                                 |
| Inner box height | 135 cm                                 |
| Load bed height  | 57 cm                                  |
| Netto height     | 121 cm                                 |
| Roof-rack        | None                                   |
| Sidedoors        | 1                                      |
| Side windows     | 1                                      |
| Back doors       | Double door                            |

### Chairs

|                 |         |
|-----------------|---------|
| Number of seats | 3       |
| Seat cover      | leather |

### Remarks

|         |                                  |
|---------|----------------------------------|
| Remarks | ac automaat EURO6 cruise control |
|---------|----------------------------------|

### Tyres/Wheels

|            |   |
|------------|---|
| Sparewheel | ✓ |
|------------|---|

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 225/55R17,0  
coil spring suspension  
Disc brakes



Tire size: 225/55R17,0  
coil spring suspension  
Disc brakes

## Contact information



info@kleyn.com

Tel: +31 183 668 444

## Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements