

MERCEDES-BENZ VITO 114 ac automaat EURO6



Itemno 318223
Kind Van
Specification Closed Van
Matriculation year 2023 / 09
Mileage 33,870 km

Chassisnumber
W1VVKBEZ6P4222413

Technical condition

Remarks
clima automaat EURO6 carplay navi
(A15)



Price € 26950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration	4x2
Loading Capacity	838 kg
Own weight	1,962 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	✓
Wheelbase	320 cm

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	2
Parking assistance	Front and back
Electric windows	✓
Electric mirrors	✓
Partition	✓
Radio/cassette	✓
GPS navigation	✓
Color	white
Heated mirrors	✓
Reversing camera	✓
Lighting type	Halogen lamps
Speed limiter	✓
Climatecontrol	✓
Bluetooth	✓

Drivetrain

Engine capacity	100 Kw (136 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Automatic
Speed limiter	✓
Power steering	✓
ABS	✓
ASR	✓
Starter battery	✓

Superstructure

Build kind	L2H1 – Middellange wielbasis, laag dak
Inner box length	245 cm
Inner box width	164 cm
Inner box height	132 cm
Load bed height	62 cm
Netto height	121 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

Doors

Central locking	✓
-----------------	---

Chairs

Number of seats	2
Seat cover	cloth
Chair adjustment	Manually

Remarks

Remarks	clima automaat EURO6 carplay navi
---------	-----------------------------------

Tyres/Wheels

Sparewheel	✓
Spare tire profile	5 %
Tire type	All weather tyres

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/65R16
coil spring suspension
Disc brakes



Tire size: 205/65R16
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements