

FORD TRANSIT 2.0 Bakwagen Laadklep!



Itemno 318240
Kind Van
Specification Closed box
Matriculation year 2020 / 08
Mileage 123,534 km

Chassisnumber
WF0AXXTTRALR06867

Technical condition

Remarks
Bakwagen Laadklep Deuren Airco 130Pk
(A15)

Price € 20900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration 4x2
Own weight 2,730 kg
Gross vehicle weight 3,500 kg
Wheelbase 393 cm

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Radio/cassette ✓
GPS navigation ✓
Color white
Heated mirrors ✓
Lighting type Halogen lamps
Climatecontrol ✓
Bluetooth ✓

Drivetrain

Engine capacity 96 Kw (130 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓
Starter battery ✓

Superstructure

Build kind L4H1 - Extra long wheelbase,
Low roof
Inner box length 423 cm
Inner box width 203 cm
Inner box height 220 cm
Load bed height 88 cm
Netto height 210 cm
Roof-rack None
Back doors Double door

Doors

Central locking ✓

Chairs

Number of seats 3
Seats configuration 1+2
Seat cover cloth
Chair adjustment Manually

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift make D Hollandia
Tail-lift material steel and aluminium
Tail-lift size 210x145

Remarks

Remarks Bakwagen Laadklep Deuren
Airco 130Pk Euro6 Navi!

Tyres/Wheels

Sparewheel ✓
Spare tire profile 8 %
Tire type Summer tyres

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Taillift

Controls

System

Tyres/Wheels

Tyres



1



Tire size: 235/65R16
coil spring suspension
Disc brakes

2



Tire size: 235/65R16
spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements