

VOLKSWAGEN TRANSPORTER 2.0 TDI BULLI EURO6

KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES



Itemno 318437
Kind Van
Specification Closed Van
Matriculation year 2023 / 01
Mileage 200,827 km

Chassisnumber
WV1ZZZ7HZPH037870

Technical condition

Remarks
BULLI EURO6 clima automaat LED carplay
(A15)



Price € 29950

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Configuration	4x2
Loading Capacity	971 kg
Own weight	1,829 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Wheelbase	340 cm
Aluminium rims	✓

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	2
Parking assistance	Front and back
Electric windows	✓
Electric mirrors	✓
Partition	✓
Radio/cassette	✓
Carplay	✓
GPS navigation	✓
Heated mirrors	✓
Lighting type	Led lamps
Bluetooth	✓

Drivetrain

Engine capacity	110 Kw (149 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓
Starter battery	✓

Superstructure

Build kind	L2H1 – Middellange wielbasis, laag dak
Inner box length	280 cm
Inner box width	157 cm
Inner box height	131 cm
Load bed height	60 cm
Netto height	128 cm
Roof-rack	None
Back doors	Double door

Doors

Central locking	✓
-----------------	---

Chairs

Number of seats	2
Seats configuration	1+1
Seat cover	cloth
Chair adjustment	Manually

Remarks

Remarks	BULLI EURO6 clima automaat LED carplay digidash cruise control navi 150 pk
---------	--

Tyres/Wheels

Tire type	Winter tyres
-----------	--------------

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 235/55R17
coil spring suspension
Disc brakes



Tire size: 235/55R17
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements