FORD TRANSIT CUSTOM 2.0 L1H1 Navi Euro6



Itemno Kind Specification Matriculation year Mileage Chassisnumber

318559 Van Closed Van 2021/04 103,244 km

WF0YXXTTGYMJ63284



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Configuration Own weight Gross vehicle weight Wheelbase

Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Partition Radio/cassette Carplay **GPS** navigation Color Heated mirrors Reversing camera Lighting type Speed limiter Laneassist Seat heating Bluetooth Blind spot sensor

4x2 2,022 kg 3,200 kg 293 cm

single cabin

1 Front and back

white

Halogen lamps

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Speed limiter Number of Gears Power steering ABS ASR Starter battery

Superstructure

Build kind

Inner box length Inner box width Inner box heigth Load bed heigth Roof-rack Sidedoors Back doors Workshop equipment

Doors

Central locking

Chairs

Number of seats Seats configuration Seat cover Chair adjustment

Remarks Remarks

96 Kw (130 Hp) diesel 6 Timing belt Manual

6

L1H1 - Short wheelbase, Low roof 247 cm 172 cm 138 cm 52 cm None Double door

3 1+2 cloth Manually

L1H1 Navi Airco Cruise Control WP-Inrichting PDC Euro6 131 PK!

Contact information



info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

FORD TRANSIT CUSTOM 2.0 L1H1 Navi Euro6



Itemno Kind Specification Matriculation year Mileage Chassisnumber WF0YXXTTGYMJ63284

318559 Van Closed Van



2021 / 04 103,244 km



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Tyres/Wheels

Sparewheel Spare tire profile Tire type

5 % Winter tyres

Contact information




info@kleyn.com Tel: +31 183 668 444 Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	
Tyres	




P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Contact information



info@kleyn.com Tel: +31 183 668 444

Legenda for inspection report

	Very good state
	Good state
00000	Reasonable state
00000	Moderate state
00000	Does not meet requirements