

RENAULT TRAFIC



Itemno 318770
 Kind Van
 Specification Closed Van
 Matriculation year 2017 / 11
 Mileage 219,721 km
Chassisnumber
 VF1FL000559187500

Technical condition 
Remarks

(A15)

Price € 9950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
 P.O. Box 3
 4214 ZJ Vuren
 Zeiving 12
 4214 KT Vuren
 The Netherlands

IBAN: NL32RABO0317847430
 SWIFT/BIC: RABONL2U

KvK 11044363
 BTW/VAT NL807901337B01

Equipment

Chassis

Configuration 4x2
 Towing bracket ✓
 Wheelbase 310 cm
 Aluminium rims ✓

Cabin

Cabin type single cabin
 Cruise control ✓
 Airconditioning ✓
 Number of airbags 2
 Parking assistance None
 Electric windows ✓
 Electric mirrors ✓
 Partition ✓
 Radio/cassette ✓
 GPS navigation ✓
 Color white
 Heated mirrors ✓
 Reversing camera ✓
 Lighting type Halogen lamps
 Speed limiter ✓
 Bluetooth ✓

Drivetrain

Engine capacity (0 Hp)
 Fuel type diesel
 Distribution type Timing chain
 Gearbox kind Manual
 Speed limiter ✓
 Number of Gears 6
 Power steering ✓
 ABS ✓
 ASR ✓
 Starter battery ✓

Superstructure

Inner box length 230 cm
 Inner box width 162 cm
 Inner box height 137 cm
 Load bed height 64 cm
 Netto height 132 cm
 Roof-rack None
 Sidedoors 1
 Back doors Double door

Doors

Central locking ✓

Chairs

Number of seats 3
 Seat cover cloth
 Chair adjustment Manually

Tyres/Wheels

Sparewheel ✓
 Spare tire profile 6 %
 Tire type Winter tyres

Contact information




info@kleyn.com
 Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 245/45R18
coil spring suspension
Disc brakes



Tire size: 245/45R18
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements